Specificație tehnică

1. PRODUCT IDENTIFICATION / *IDENTIFICARE PRODUS*			
Brand name / *Denumire brand*	**Promax**		
Product name / *Denumire produs*	**Praf de curatat**		
Declared Net weight or volume / *Volumul/Greutatea net(a) declarat(a)*	500 g	with "e"	
Additional product description (e.g. grading, pieces, numbers etc.) *Descriere suplimentara produs (de ex. clasificare, bucati, numar, etc.)*			
Variant(s) / *Variante*	Alb, Verde, Galben, Roz		
SF- *standard de firmă*	3/1999		
Transport condition [temp., humidity etc.] *Conditii de transport (temp., umiditate, etc.)*	$5^{O}C$ - $25^{O}C$		
Storage condition [temp., humidity etc.] *Conditii de depozitare (temp., umiditate, etc.)*	$5^{O}C$ - $25^{O}C$		
Shelf life after production [days] *Termen de valabilitate dupa producere (zile)*	1095		

2. IDENTITY OF THE PRODUCER / PACKAGER / SUPPLIER / *IDENTITATEA PRODUCATORULUI/AMBALATOR/FURNIZOR*		
2.1 PRODUCTION & PACKAGING *2.1. PRODUCERE SI AMBALAJ*	**MANUFACTURING ADRESS** *ADRESA DE PRODUCERE*	**PACKAGING ADDRESS, when different from manufacturing address** *Adresa de ambalare, daca difera de adresa de producere*
Name / *Denumire*	**SC Romchim Srl**	
Address / *Adresa*	Str.Câmpului , nr.18	
Tel & Fax /	0365.404.948 / 0365.805.808	
e-mail	office@romchim.ro	
Approval number or Registration number [when applicable] *Numarul de inregistrare*	J26/905/1998	
Cerification / Notification/ *Certificări / avizări*	YES	
	ISO 9001 si ISO 14001	

3. INGREDIENTS / *INGREDIENTE*			
INGREDIENTS IN DECREASING ORDER [ADDITIVES ADDITIONALLY WITH "E"-NUMBER] PLEASE DETAIL COMPOUND INGREDIENTS WHEN RELEVANT *Ingredientele in ordine descrescatoare (aditivi suplimentar cu numar E) Detaliati ingredientele compuse dupa caz*	**COUNTRY / PLACE OF ORIGIN** *Tara / Locul de origine*	**% IN THE PRESCRIPTION** *% in prescriptie*	**% IN THE FINAL PRODUCT [if different]** *% in produsul finit (daca difera)*
Substante abrasive de suprafata		>30%	
Sulfati		5-10%	
Fosfati		<1 %	
Silicati		<1 %	

Parfum			

4. PHYSICAL AND CHEMICAL CHARACTERISTICS / *CARACTERISTICI FIZICO CHIMICE*

PARAMETER / *Parametru*	**UNIT /** *Unitate*	**TARGET VALUE /** *Valoarea planificata*	**TOLERANCE /** *Toleranta*	**METHOD OF CONTROL /** *Modalitatea de control*
Appearance /*Aspect*		Pulbere fina		Organoleptic
Color /*Culoare*		Alb, Verde, Galben, Roz		Organoleptic
Smell / *Miros*		Parfumat		Organoleptic
pH-			9.5-11	pH- metru
Consistency, texture / *Consistența, textura*				
Density / *Densitate*	g/cm^3		1-1.2	Raport volum/greutate

5. INSTRUCTION FOR USE / METHODE OF PREPARATION / *INSTRUCTIUNE DE UTILIZARE / METODA DE PREPARARE*

Promax Praf de curatat se foloseste in gospodarie pentru curatatul obiectelor casnice emailate, faianta si inox. Cantitate de praf de curatat necesara este in functie de gradul de murdarie depus pe obiectul ce urmeaza a fi curatat.

6. DIMENSION OF RETAIL, WHOLESALE AND TRANSPORT PACKAGING / *DIMENISIUNILE AMBALAJULUI*

MEASUREMENTS [such as length, calibre, number of pieces, weight etc.] / *Masuri (lungime, calibre, nr. Buc, greutate, etc)*

	Material / *Material*	Dimension [L x W x H] / *Dimensiuni (LxLxA)*	Weight / Volume *Greutate / Volum*
RETAIL Packaging / *Ambalaj comercial*	Fl. HDPE	6.5/6.5/20	12 buc/bax
WHOLESALE Packaging / *Ambalaj en-gros*	Folie termo		

7. CONDITIONS OF HANDLING, STORAGE AND DISPOSAL / *CONDITII DE MANIPULARE, DEPOZITARE SI ELIMINARE*

Manipulare- în condiții normale de lucru nu prezintă nici un pericol.
Depozitare- în ambalajul original, la temperaturi cuprinse între 5-15^{o}C.
Eliminare- flacoanele nu se elimină cu conținut în ele. După golirea completă a acestora, ambalajele se colectează selectiv, în vederea eliminării conform legislației în vigoare privind regimul deşeurilor.

8. PHRASES AND FIRST AID MEASURES / *PERICULOSITATE, MĂSURI DE PRIM AJUTOR*

Produsul **Promax Praf de curatat** în stare concentrată este clasificat ca fiind un produs **nepericulos** având urmatoarele fraze de precauțiune:

P102 – A nu se lăsa la îndemâna copiilor.
P305 + **P351** + **P338** – ÎN CAZ DE CONTACT CU OCHII: clătiți cu atenție cu apă timp de mai multe minute. Scoateți lentilele de contact, dacă este cazul şi dacă acest lucru se poate face cu uşurință. Continuați să clătiți.
P261 – Evitați să inspirați praful/fumul/gazul/ceaţa/vaporii/spray-ul.